

FLOATING STONES
779 GREAT NORTHERN HIGHWAY
DONNYBROOK 6239
Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T110 L , Serial Number 585

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T110 L, serial number 585.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX07 Schneider material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



TILLETT NATURAL STONE INDUSTRIES
162 WEST TERRACE
HINDMARSH 5007
Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T522, Serial Number 36

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T522, serial number 36.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX47, XBTK screen, other electrical equipment

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



SANDMAN STONE
7 HEPNER PLACE
NORTH GEELONG
NORTH GEELONG VIC 3215
Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 16

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 16.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



EUROPEAN MARBLE CENTER 6 6A LEVANSWELL ROAD VICTORIA 3189 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 17

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 17.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



DINDLOY PTY LTD STONE AND TILE CENTRE MORNINGTON 3931 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 18

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 18.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



CARUSO GROUP MARBLE FACTORY 4 15 RAMAGE STREET BAYSWATER VIC 3153 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 19

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 19.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



GRANITE INNOVATIONS
3 WILDON STREET
BELLEVUE 6056WA
Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 22

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 22.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



TILLETT NATURAL STONE INDUSTRIES 162 WEST TERRACE HINDMARSH 5007 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 23

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 23.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



DINDLOY PTY LTD STONE AND TILE CENTRE MORNINGTON 3931 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 26

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 26.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



PDA MARBLE GRANITE 26 KENDALL NORTH AVENUE QUEANBEYAN 2620 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 60

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 60.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



ANDREW JOHN SYDES 141 SOUTH BRIDGENORTH ROAD BRIDGENORTH - TASMANIE 7277 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 66

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 66.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



EXCLUSIVE MARBLE AND GRANITE UNIT 7/21 CAPPELA CRES MOORABBIN 3189 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 90

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 90.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



HUTCHBY STONE 58, Mc Eachan EDMONTON 4869 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 96

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 96.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



LODGE BROS 331 DAREBIN ROAD VICTORIA 3072 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 , Serial Number 109

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55, serial number 109.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX17 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



MOORABBIN MARBLE & GRANITE 17 NELLBERN ROAD MOORABBIN 3189 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 ADVANCE, Serial Number 206

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55 ADVANCE, serial number 206.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: Mechanical and electrical equipment

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control. We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



AUSTRALIAN MAJESTIC MARBLE AND GRANITE 9/316 BRISBANE ROAD ARUNDEL QLD, 4240 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 ADVANCE, Serial Number 216

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55 ADVANCE, serial number 216.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: Mechanical and electrical equipment If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



AFFORDABLE STONE BENCHTOPS 999A Fairfield Road ROCKLEA 4106 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 ADVANCE, Serial Number 217

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55 ADVANCE, serial number 217.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: Mechanical and electrical equipment

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control. We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



TUFF STONE PTY LTD 11 FURY COURT CLAYTON SOUTH VICTORIA 3169 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 ADVANCE, Serial Number 221

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55 ADVANCE, serial number 221.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: Mechanical and electrical equipment

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



ADRIATIC STONE
2 KYLIE PLACE
CHELTENHAM 3192
Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 ADVANCE, Serial Number 231

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55 ADVANCE, serial number 231.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: Mechanical and electrical equipment

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control. We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



BALTIC STONEMASON PROFESSIONALS
BALTIC STONEMASON PROFESSIONAL
S
DANDENONG 3175
Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 CO, Serial Number 77

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55 CO, serial number 77.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX37 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



ALLURE LIVING 5/4 WARMAN ROAD PERTH 6065 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 CO, Serial Number 82

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55 CO, serial number 82.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX37 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



STONEWARE PRODUCTIONS PTY LTD 49 - 51 BARNETT AVENUE GLYNDE SOUTH AUSTRALIA 5070 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 CO, Serial Number 97

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55 CO, serial number 97.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX37 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



STONEWARE PRODUCTIONS PTY LTD 49 - 51 BARNETT AVENUE GLYNDE SOUTH AUSTRALIA 5070 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T55 CO, Serial Number 98

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T55 CO, serial number 98.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: TSX37 material

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



GOSFORD MARBLE AND GRANITE 323, MANNS ROAD WEST GOSFORD NSW 2250 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T108 V1.2 L, Serial Number 174

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T108 V1.2 L, serial number 174.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: Schneider Automatism TSX07 without xbthm screen

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service



BRAVVO 26, VALES STREET MALAGA, WA 6090 Australie

Subject: Important Information Regarding the End of Technical Support for Certain Components of Your Machine T108 V2.1 L, Serial Number 307

Dear Sir/Madam,

We are contacting you as a Thibaut customer, using the machine T108 V2.1 L, serial number 307.

We would like to inform you that, due to technological advancements and the obsolescence of materials from suppliers (production cessation...), we will no longer be able to provide technical support for certain components as of today. However, please note that your machine remains functional in its current state.

The designation of the affected hardware components is: Schneider Automatism TSX07 with xbthm screen

If there are alternatives available outside of Thibaut, we will be sure to suggest them to you.

If you have any questions, please do not hesitate to reach out to us via our Thibaut Web portal.

We sincerely thank you for your loyalty and regret this situation, which is beyond our control.

We remain committed to providing you with innovative and quality solutions.

Best regards,

Thibaut Customer Service